

Scrap wood removed from northwest corner of the house. Bush trimmed away from house.



Construction debris from the southwest corner of the garage was sent to the transfer station.



Plum tree branches growing over southwest corner of the house now cut well back.



Cedar fencing removed from east side of house.

